



## SOFTWARE UPDATE

# GET THE MOST OUT OF YOUR BLACKBERRY BOLD 9930.

Verizon Wireless is pleased to announce a new software update, 7.1 Platform 5.1.0.137 Release 457, for your BlackBerry® Bold™ 9930.

**Verizon Wireless and RIM encourage you to download this update.**

### Device Features

- + Device will no longer repeatedly indicate that new software has been installed.
- + Device will no longer reset while connected to a charging source.
- + Device displays the correct wireless service provider while making calls or sending text messages.
- + While in a global roaming condition, connect to a previously registered CDMA network without experiencing lengthy search periods.
- + Improvements in home screen responsiveness and reduced touch screen lockups.
- + No longer experience delays in audio reception or unexpected call termination.
- + Improvements in device stability during Push to Talk calls.
- + Device will no longer restart unexpectedly when making a Push to Talk call to a newly created group.
- + Improvements to audio quality during playback for audio files downloaded using the V CAST application.
- + The zoom in and zoom out function on the browser application renders the page properly.
- + When downloading an application, the device will display the correct number of bytes being downloaded.
- + Device now supports Commercial Mobile Alert System (CMAS).
- + Device now supports Wi-Fi Mobile Hotspot (MHS).

### Email & Messaging

- + Duplicate text messages will no longer display in the Messaging application.
- + Improvements in Visual Voice Mail.



**BlackBerry Bold 9930**

For step-by-step instructions on how to perform the download, please visit [verizonwireless.com/bold9930support](http://verizonwireless.com/bold9930support)