



SOFTWARE UPDATE

GET THE MOST OUT OF YOUR DROID INCREDIBLE 2 BY HTC.

Verizon Wireless is pleased to announce a new software update, 5.10.605.9; Radio: 20.32W.30.0813U_1.09.01.1111, for your DROID Incredible 2 by HTC.

Verizon Wireless and HTC encourage you to download this update.

Security Features

- + Includes Google BT/DigiNoTar security patch.
- + Includes Google security patch for upgrading libpng to 1.2.46.
- + Includes Wi-Fi password security patch.

Device Features

- + Support local video playback when in Airplane Mode.
- + 5 bar Received Signal Strength Indicator (RSSI) support.
- + Improvements to Clock and Alarm features.
- + The "Disable While Roaming" selection will work accurately when roaming in Canada.
- + Update Sync & Connect configuration to enable Push email sync during off-peak hours.



**DROID INCREDIBLE 2
by HTC®**



For step-by-step instructions on how to perform this download, visit verizonwireless.com/droidincredible2support