

## SOFTWARE UPDATE

# BLACKBERRY® CURVE™ 9370

Verizon Wireless is pleased to announce a software update — Software version 5 software 7.1 Release 2879 (App: 7.1.0.1066; Platform: 5.1.0.699) — designed to improve the performance of your BlackBerry® Curve™ 9370 smartphone.



BlackBerry® Curve™ 9370

### DEVICE ENHANCEMENTS

Enhancements have been made to the following areas:

- Push to Talk connectivity has been enhanced
- Bluetooth connectivity has been enhanced
- Audio boost feature has been enhanced
- The number of necessary device resets has been reduced
- New time zone message will now provide more details
- Download OTASL patch without receiving this error message “Download software is invalid. Try again later or update using BlackBerry Desktop Manager on your computer”

### NEW CAPABILITIES

Support has been added to the following areas:

- Enhanced Caller ID (Caller Name ID)
- Wi-Fi radio can be enabled/disabled when in emergency call back mode
- Wi-Fi radio will no longer activate when in tethering mode
- Private/restricted numbers will now appear as “restricted” (instead of “001”)

For step-by-step instructions on how to perform the download, please visit [verizonwireless.com/blackberrycurve9370support](http://verizonwireless.com/blackberrycurve9370support)

# BLACKBERRY® CURVE™ 9370

---

## IMPROVEMENTS

---

Improvements have been made to the following areas:

- Internet Browser security has been improved
- Call volume when using a wired headset
- Battery life
- Multimedia and picture messaging reliability
- Software installation and download processes
- VZAccess Manager file downloads
- Camera and camera mode
- Video Player, sending videos and receiving video content
- Trackpad responsiveness
- Video quality when using YouTube application
- Error message when using YouTube application has been reduced

For step-by-step instructions on how to perform the download,  
please visit [verizonwireless.com/blackberrycurve9370support](http://verizonwireless.com/blackberrycurve9370support)